

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARYCONDITION  
CERTIFICATENo. 57103 05/05/2022/1Date: 04/05/2022

It is certified that an inspection team headed by Mr. Rahul  
Suryawanshi Asst. Engg. Zone - 12 (Name of  
Officers with designation) from Indore Municipal Corporation Hassidhi Zone No. 1  
(Name of Department/Office) inspected the

Bal Niketan higher Secondary School 62 Pagnis Paga indore  
(Name & Address  
of the School) on 03/05/2022 and found that the Bal Niketan Higher  
Secondary School (Name of school) has  
safe drinking water facilities for the students and members of staff of the institution  
and is maintaining the hygienic sanitation condition in the school building & the  
campus as per the norms prescribed by the Central/State/U.T Govt.

The above valid for a period of Three Years

Signature with Seal

: \_\_\_\_\_

Name: \_\_\_\_\_

Designation: \_\_\_\_\_

जल प्रदाय क्षेत्र क्र. 12  
इ. न. पा. नि., इन्दौर

To  
Bal Niketan Higher Secondary  
School 62 Pagnis  
Paga indore - 452007

(Name &amp; Address of the Institution)